

Download Johnson Outboard Manual Release Valve

Re: 90 90hp johnson tilt trim manual release valve Remove the whole tilt & trim unit. Disconnect and pull the wiring from the cowl, turn the release screw, raise the motor manually, set the lock, unbolt the unit from the mounts, drive the pin out of the center ram, push the center ram in, and the whole thing will come up and out. MarineEngine.com carries Evinrude Johnson OMC 0435340 - Manual Release Valve and Seal and outboard motor parts for Johnson, Evinrude, Mercury, Mariner and Mercruiser sterndrives. Close the manual release valve if the system won't move in either direction. If the unit still won't move, replace the manual release valve; if the symptoms disappear, the relief valve was the cause. If not, remove and replace the coupling on the trim motor. If the problem persists, install a pump manifold. My guess is you have a 1993 or newer OMC/ Evinrude, Johnson, engine? I have had the same issue on both of my 1996 T/T Evinrude systems and my guess is you will have to remove the entire T/T system from the engine ("FasTrack" is the name of this T/T system for the record) to remove the manual release valve.